

# Slim Shaper®

ZARC

	MFD	TAPER	Ø
ZS1	0,80	2-6%	15
ZS2	0,80	4-3%	20
ZS3	0,84	4-3%	25

# SlimShaper®



**KFile**  
#10

Glide Path



**ZS1**  
RPM: 500  
Torque: 3

Shaping



**ZS2** **ZS3**  
RPM: 500  
Torque: 3

Finishing



*Irrigate, recapitulate with a 10 file and re-irrigate after removing each rotary file*